Test Report No. VNT/H/25/001694
Dated 07 AUG 2025

Add value.
Inspire trust.

Note: This report is issued subject to the Testing and Certification, Validation and Verification Regulations of the TÜV SÜD Group and the General Terms and Conditions of Business of TÜV SÜD Vietnam Co. Ltd. In addition, this report is governed by the terms set out within this report.

Applicant	:	**CÔNG TY CỔ PHẦN SỢI AN VIỆT**
Address	:	Lô 2-4, Đường số 7, KCN Tân Đức, Xã Đức Hòa, Tỉnh Tây Ninh, Việt Nam
Attention	:	Ms. Minh
Received Date	:	Jul. 29, 2025
Test Period	:	From Jul. 29, 2025 to Aug. 07, 2025
Sample Description	:	Non-woven Fabric Polypropylene
Color	:	Black
Wood Typer or specie/ Material	:	Non-woven Fabric
Country Of Origin	:	Viet Nam
Fiber content (For fabric/PU/vinyl)	:	Polypropylene

VILAS 487

The results reported herein have been performed in accordance with the terms of accreditation under the Vietnam Bureau of Accreditation. Tests marked "Not Accredited" in this Report are not included in the BoA Accreditation Schedule for our laboratory.

Laboratory:
TÜV SÜD Vietnam Co. Ltd.
Lot III-26, Street 19/5A, Industry Group III, Tan Binh I.P, Tay Thanh Ward, Ho Chi Minh City, Vietnam

Phone :+ 84-28-62678506
Fax : +84-28-62678511
E-Mail: info.vn@tuvsud.com
https://www.tuvsud.com/vi-vn

Regional Head Office:
TÜV SÜD Asia Pacific Pte. Ltd.
15 International Business Park
TÜV SÜD @ IBP
Singapore 609937

Result summary/ conclusion:

Test parameter(s)	Conclusion
The Furniture & Furnishings (Fire) (Safety) Regulations 1988. SI No. 1324 (amended 1989, 1993 and 2010), Schedule 4 Part II, The Cigarette Test (Refer to BS 5852: Part 1:1979, source 0)	Pass / See Result(s)
The Furniture & Furnishings (Fire) (Safety) Regulations 1988. SI No. 1324 (amended 1989, 1993 and 2010), Schedule 5 Part III, The Match Test (Refer to BS 5852: Part 1:1979, source 1)	Pass / See Result(s)

Note(s):

- The submitted sample(s) is Not Drawn by the Laboratory.
- This testing result is only valid on the tested sample.
- The test report shall not be reproduced except in full without the written approval of the laboratory.
- Conclusion on Pass/Fail are based on the test result from the actual received sample(s).
- Test Condition for Invisible cover material:

Prior to testing the sample was conditioned at indoor ambient conditions for 72 hours followed by conditioning in a standard atmosphere having a temperature of 20±5°C and a relative humidity of 50±20% RH for a minimum of 16 hours.

TEST RESULT(S):

The Furniture & Furnishings (Fire) (Safety) Regulations 1988. SI No. 1324 (amended 1989, 1993 and 2010), Schedule 4 Part II, The Cigarette Test (Refer to BS 5852: Part 1:1979, source 0)

Specimen no.		**Specimen A**	**Specimen A**
Testing position		Left	Right
Ignition (I) / Did not ignite (DIN) / Ignite but extinguished (IBE) / Surface flash burn (SFB)		DIN	DIN
Progressive smouldering (PS), Flaming (F) or Did not Ignite (NI)		NI	NI
Duration of	Ignition source	18 min, 43 sec	18 min, 46 sec
	Flames (min, sec)	0 sec	0 sec
	Smoke (min, sec)	10 sec	11 sec
Finial examination of progressive smouldering (9.4)		No	No
Reason for failure (Reference to failure code)		/	/
Comments & observations		/	/
Overall result		**Pass**	**Pass**

Failure Code:

9.2.4 - Progressive smouldering or flaming of the upholstery components is observed at any time within a period of 1 hour of the placement of the cigarette.

The Furniture & Furnishings (Fire) (Safety) Regulations 1988. SI No. 1324 (amended 1989, 1993 and 2010), Schedule 5 Part III, The Match Test (Refer to BS 5852: Part 1:1979, source 1)

Specimen no.		**Specimen B**	**Specimen B**
Testing position		Left	Right
Ignition (I) / Did not ignite (DIN) / Ignite but extinguished (IBE) / Surface flash burn (SFB)		DIN	DIN
Progressive smouldering (PS), Flaming (F) or Did not Ignite (NI)		NI	NI
Duration of	Ignition source	20 sec	20 sec
	Flames (min, sec)	0 sec	0 sec
	Smoke (min, sec)	9 sec	11 sec
Finial examination of progressive smouldering (9.4)		No	No
Reason for failure (Reference to failure code)		/	/
Comments & observations		/	/
Overall result		**Pass**	**Pass**

Failure Code:

9.3.4 - Flaming or progressive smouldering in the interior and/or cover after 120 seconds of the removal of the burner tube.

PHOTO(S) OF SUBMITTED SAMPLE(S) FOR TESTING:



Non-woven Fabric Polypropylene

Customer inquiries, please contact:
Nhut Phan, Tel: +84 28 6267 8507, Ext: 123; email: hoang-nhut.phan@tuvsud.com

Phan Hoang Nhut	Tran Thi Lien
Senior Executive - Customer Service	Manager - Hardlines Laboratory
Reviewer	Authorizer

Please note that this Report is issued under the following terms :

1. This report applies to the sample of the specific product/equipment given at the time of its testing. The results are not used to indicate or imply that they are applicable to other similar items. In addition, such results must not be used to indicate or imply that TÜV SÜD Vietnam Co. Ltd. approves, recommends or endorses the manufacturer, supplier or user of such product/equipment, or that TÜV SÜD Vietnam Co. Ltd. in any way "guarantees" the later performance of the product/equipment. Unless otherwise stated in this report, no tests were conducted to determine long term effects of using the specific product/equipment.

2. The sample/s mentioned in this report is/are submitted/supplied/manufactured by the Client. TÜV SÜD Vietnam Co. Ltd. therefore assumes no responsibility for the accuracy of information on the brand name, model number, origin of manufacture, consignment or any information supplied.

3. Nothing in this report shall be interpreted to mean that TÜV SÜD Vietnam Co. Ltd. has verified or ascertained any endorsement or marks from any other testing authority or bodies that may be found on that sample.

4. This report shall not be reproduced wholly or in parts and no reference shall be made by the Client to TÜV SÜD Vietnam Co. Ltd. or to the report or results furnished by TÜV SÜD Vietnam Co. Ltd. in any advertisements or sales promotion.

5. Unless otherwise stated, the tests were carried out in TÜV SÜD Vietnam Co. Ltd., Lot III-26, Street 19/5A, Industry Group III, Tan Binh I.P, Tay Thanh Ward, Ho Chi Minh City, Vietnam.

6. The tests carried out by TÜV SÜD Vietnam Co. Ltd. and this report is subject to TÜV SÜD Vietnam Co. Ltd.'s General Terms and Conditions of Business and the Testing and Certification, Validation and Verification Regulations of the TÜV SÜD Group.

Effective 03 July 2025

-- END OF TEST REPORT --