

ote TESTING REPORT

399 Jihai Road,Dama Town, Tongxiang City, Zhejiang Province, China			
TEL: 0573-88931080 www.otefabrics.com			
NO. OTELAB20260722-16	TESTED BY Wang xiaogang	TESTED DATE 2026/7/16	REPORT DATE 2026/7/22
ITEM: BETTER-402 / BS5852 ,batch no. #2605003. 			END USE SOFA
Testing item	Standard	Result	Comment
1.Flammability	BS 5852:1979 schedule 5 Part I Schedule 4 Part I	Meet	Pass



Detailed testing information

1. Flammability Test(BS 5852 Part 1: 1979, Match Test)

1.1 The test, specified in schedule 5 Part I of The Furniture and Furnishings (Fire)(Safety) Regulations 1988(as amended in 1989, 1993 and 2010), is based on BS 5852 part 1: 1979 using ignition source 1-match test for 20 seconds

1.2 To assess the ignitability of visible cover with Standard filling material used in upholstered components when subjected to ignition flame.

1.3 The following test results relate only to the ignitability of the combination of material under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.

1.4 Conditioning: ①72 hours indoor ambient and at least 16 hours of 20±5 °C, 50±20% relative humidity.②Testing Atmosphere: 15-30°C, 20-70% relative humidity.③Flame Retardant Finishing Of Visible Cover: Yes④Soaking Condition:Clause 4.2-4.5 of BS 5651: 1978 As Modified By The Furniture and Furnishings(Fire)(Safety) Regulations 1988,⑤ 30 minutes at 40°C, Line Dry.⑥Performance Requirement: Clause 9 of BS 5852 part 1: 1979

1.5 Test Result

①progressive Smoldering Failure

Item	Detailed information	1 ST Test	Retest
A	Evidence of progressive smoldering in the interior and/or cover after 120 seconds of the removal of burner tube	NO	NO
B	On final examination progressive smoldering is observed on the assembly dismantle and examined it internally.	NO	NO

②Flaming Failure

Item	Detailed information	1 ST Test	Retest
A	Evidence of the flaming in the interior and/or cover after 120 seconds of the removal of the removal of the burner tube	NO	NO

Fabric	Ignition	Time to Extinction after Removal of Burner			
		Flaming Ceased Time		Smoking Ceased Time	
		Minutes	Seconds	Minutes	Seconds
1	1	0	0 "	0	20 "
RETEST	1	0	0"	0	23 "

Remark: No Was not observe

2 .Flammability Test(BS 5852: Part 1: 1979, Cigarette Test)

2.1 The Test, Specified In Schedule 4 Part I Of The Furniture And Furnishing(Fire) (Safety)Regulations 1988 AS Amended In 1989, 1993 And 2010), Is Based On BS 5852 Part 1: 1979 Using Ignition Source-cigarette.

2.2 To Assess The Ignitability Of Visible Cover With Standard Filling Material Used In Upholstered Components When Subjected To A Smoldering Cigarette. 2.3 The Following Test Results Relate Only To The Ignitability Of The Combination Of Materials Under The Particular Conditions Of Test; They Are Not Intended As A Means Of Assessing The Full Potential Fire Hazard Of The Materials In Use

2.4 Conditioning: ① 72 hours Indoor Ambient And At Least 16 hours Of 20±5°C, 50±20% Relative Humidity. ② Testing Atmosphere: 15-30°C, 20-70% Relative Humidity ③ Flame Retardant Finishing Of Visible Cover: Yes. ④ Soaking condition: Clause

4.2-4.5 of BS 5651: 1978 As Modified By The Furniture and Furnishings (Fire)(Safety) Regulations 1988, 30 minutes at 40°C, Line Dry. ⑤ Performance Requirement: Clause 9 Of BS 5852 Part 1: 1979

2.5 Test Result:

① Progressive Smoldering Failure

Item	Detailed information	1 ST Test	Retest
A	Evidence of progressive smoldering in the interior and/or cover During Combustion.	NO	NO
B	Progressive Smoldering of The Upholstery Components is Observed At Any Time within A period of One Hour of The Placement of The Cigarette.	NO	NO
C	On Final Examination Progressive Smoldering is Observed on the Assembly Dismantle and Examined It internally.	NO	NO

② Flaming Failure

Item	Detailed information				1 ST Test	Retest
A	Evidence of the flaming in the interior and/or cover During Combustion.				NO	NO
B	Flaming of The Upholstery Components is Observed at Any Time With A Period of One Hour of The Placement of The Cigarette.				NO	NO
Fabric Standard Filling	Ignition Source	Time to Extinction after Removal of Burner				
		Flaming Ceased Time		Smoking Ceased Time		
		Minutes	Seconds	Minutes	Seconds	
1	0	0	0	26	19	
RETEST	0	0	0	27	10	

Remark: ① No=Was not observed. ② The fabric was tested with non fire-retardant polyurethane foam type .

END OF REPORT